Permanent Magnet Magnetic Particle Capping Headsets

CLUTCH / BR



Precision Tork™

Permanent Magnet Clutches and Brakes

Precision Tork units provide constant torque independent of slip speed. They offer excellent overload and jam protection for all drive train components and also provide soft starts with zero slip when a preset torque is reached. Precision Tork permanent magnet clutches and brakes do not require maintenance and provide extremely long life.

Magnetic Particle Clutches and Brakes



Warner Electric Precision Tork magnetic particle clutches and brakes are unique because of the wide operating torque range available. Torque to current is almost linear and can be controlled very accurately. The unique features of the magnetic particle clutches and brakes make them ideal for tension control, load simulation, cycling/indexing, and soft starts and stops.

Magnetic Capping Headsets

Warner Electric Precision Tork now offers a complete line of Magnetic Capping Headsets that are a direct interchange with many major capping OEM machines. The Precision Tork headset features hysteresis technology providing a smooth, consistent application & removal torque. They are easy to install and maintain with little adjustment required. The Precision Tork headset has a unique visual scale for setting both application torque & the top load spring.



Features and Benefits	1
Special Applications	1
Applications	2
Specifications	3
Mounting Arrangements	3
Hollow Bore Units	4
Solid Shaft Units	5
Mounting Bracket	5
Heat Dissipation Charts	6
Torque Setting Charts	7
Stub Shaft Adapters	8
How to Order	8
Stainless Steel	9

Magnetic Particle Clutches and Brakes

Features and Benefits10)
Design and Operation11	1
Selection	2
Applications14	1
Clutches - Dimensions and Specifications17	7
Mounting Bracket17	7
Brakes – Dimensions and Specifications18	3
Controls	9

Magnetic Capping Headsets

Replacements	20
Features and Benefits	21
Models Available	21





Permanent Magnet Clutches and Brakes

Fast, precise torque adjustment!

Precision Tork[™] clutches and brakes

Precision Tork units provide constant torque independent of slip speed. They offer excellent overload and jam protection for all drive train components and also provide soft starts with zero slip when a preset torque is reached. Precision Tork permanent magnet clutches and brakes do not require maintenance and provide extremely long life.

Features and Benefits

Fast, precise torque adjustment

- · Torque is set with a large knurled adjustment ring.
- · Infinite adjustability between minimum and maximum settings. This allows units to be fine tuned to your unique requirement.
- Easy to read graduations.

Torque is constant with respect to speed

- · By using the Precision Tork unit, you can solve almost any torque control problem.
- Torque is extremely consistent and smooth at low, as well as high speeds.

No external control or power source

- Simple to install
- Nothing to monitor
- Unaffected by power interruption or power fluctuation
- Safe to use

Dependable performance

- · Smallest possible transition from static to dynamic torgue. Virtually eliminates the "stick-slip" phenomenon associated with friction devices.
- · Long life. The only wearing parts are the ball bearings.
- Extremely accurate. Precision Tork units out-perform all other devices at low RPM.

Versatile mounting: Easy to retrofit

- · Clutches are available with hollow bores for mounting on motor shafts or jack shafts.
- Bolt circles allow for fixed mounting, adding a pulley, or stub shaft adapters.
- · Brakes are available with solid shaft outputs.

Distributor item

- · Off the shelf availability.
- Interchangeable with competitors' products.



mounting

vary the amount of torque

Special Applications

Specials are our business...

- · Special shaft bores and keyways
- Shaft extensions
- System retrofits
- Metric bores and keyways
- Stainless steel construction
- Fixed torque units



MC4D

Long Shaft Extension

Applications

Cycling

Bottle

capping

Constant torque

hysteresis clutch.

provided by a

Unwind tension control

Brake mounted on shaft of unwind spool or bobbin.



Information required:

Full roll diameter (in.) = 6 in. Core diameter (in.) = 4 in. Average tension (lbs.) = 4 lbs. Velocity (feet per min.) = 100 fpm

How to size:

Average radius (in.) =
Full roll dia. (in.) + Core dia. (in)
4
=
$$\frac{6+4}{4}$$
 = 2.5 in.

Torque (lb.in.) =

Avg. tension (lbs.) x Avg. radius (in.) = $4 \times 2.5 = 10$ lb.in.

Information required:

Slip RPM = 500 RPM Torque = 8 lb.in. % slip time of total cycle time = 25%

How to size:

*Watts = .0118 x torque (lb.in.) x slip RPM x % slip time = .0118 x 8 x 500 x .25 = 11.8 watts Check tension range: Max. tension = Torque (lb.in.) x $\frac{2}{\text{Core dia. (in.)}} = 10 \text{ x } \frac{2}{4} = 5 \text{ lbs.}$ Min. tension = Torque (lb.in.) x $\frac{2}{\text{Full roll dia. (in.)}} = 10 \text{ x } \frac{2}{6} = 3.3 \text{ lbs.}$ Slip watts = Max. tension (lbs.) x velocity (fpm) 44.2

= 11.3 watts

Select Model MC4

Select an MC4 from the specification chart.

*Note: Consult factory if peak slip watts are extremely high or if duration of slip period is in excess of 1 minute.

Nip roll or pulley tension control



Clutch

Information required:

Pulley or nip roll diameter = 4 in. Tension = 6 lbs. Velocity = 100 fpm

How to size:

Torque (lb.in.) = Tension (lbs.) x
$$\frac{\text{Dia. (in.)}}{2}$$
 = 6 x $\frac{4}{2}$ = 12 lb.in

Slip watts =
$$\frac{\text{Tension (lbs.) x velocity (fpm)}}{44.2} = \frac{6 \times 100}{44.2} = 13.5 \text{ watts}$$

Select Model MC5

Overload protection/Torque limiting/Soft start

Motor horsepower method



Hysteresis clutch provides overload protection.



Material handling Hysteresis clutch can provide overload protection and soft start.

Information required:

Motor HP = 1/2 HP Motor RPM = 1750 RPM How to size: Torque (lb.in.) = $\frac{\text{HP x 63000}}{\text{RPM}}$ = $\frac{1/2 \times 63000}{1750}$ = 18 lb.in.

Select an MC5 from the specification chart.

Specifications

Specifications	Model Size	D Torque	Heat Dissipation (watts)	Inertia (Ibs. sq. in.)	Bending Moment (Ib. in.)	Max. RPM	Weight (Ibs.)	Bore Range/Shaft Dia. (in.)
1 a tarr	MC1.5	1–10 oz. in.	10	0.02	5	3600	10.5 oz.	1/4
	MC2	0.5–20 oz. in	. 10	0.02	5	3600	11 oz.	1/4
	MC2.5	0.5–3 lb. in.	15	0.11	10	1800	1.5	3/8, 1/2
	MC3	0.5–6 lb. in.	18	0.14	10	1800	2.5	5/16, 3/8
	MC4	0.7–11 lb. in.	22	0.32	10	1800	3.5	3/8, 1/2, 5/8
	MC5	1–30 lb. in.	72	1.72	25	1800	9.5	3/8, 1/2, 5/8, 3/4, 7/8, 1
	MC5.5	1–50 lb. in.	110	2.74	25	1800	12	3/8, 1/2, 5/8, 3/4, 7/8, 1
Hollow Bore Configurations	MC6	4–70 lb. in.	150	4.28	25	1800	12	3/8, 1/2, 5/8, 3/4, 7/8, 1
oomigurationo	MC6D	6–140 lb. in.	300	8.52	25	1800	24	1/2, 5/8, 3/4, 7/8, 1
	MC9	15-300 lb. in	. 345	65.74	50	1200	48 5/	8, 3/4, 7/8, 1, 1-1/8, 1-1/4
	MB1	0-1.1 oz. in.	3	0.001	1	3600	2.5 oz.	3/16
	MB1.5	1–10 oz. in.	10	0.02	5	3600	11 oz.	1/4
	MB2	1–20 oz. in.	10	0.02	5	3600	11.5 oz.	1/4, 3/8
	MB2.5	.5–3 lb. in.	15	0.11	10	1800	2.5	3/8, 1/2
	MB3	0.5–6 lb. in.	18	0.14	10	1800	2	3/8
	MB4	0.5–11 lb. in.	22	0.33	10	1800	3.5	1/2, 5/8
	MB5	1–30 lb. in.	72	1.76	25	1800	10	1
Solid Shaft Configurations	MB5.5	1–50 lb. in.	110	2.79	25	1800	12.5	1
	MB6	2–70 lb. in.	150	4.33	25	1800	12	1
	MB6D	6–140 lb. in.	300	8.68	25	1800	26	7/8
	MB9	15-300 lb. in	. 345	66.09	50	1200	48	1

Typical Mounting Arrangements



Brake: Typical setup for tensioning wire, film and fibers.



Typical setup for material handling, soft starts and torque limiting.

Clutch:

Stub Shaft Adapter



Clutch Coupling:

Typical setup for torque limiting protection used for labeling, capping and printing applications.

Hollow Bore Configurations





Drawing A

^B Drawing B

	Diamig/	•				3 -	
*Set scre	w adjustment			*Spanner w	rench adjustment	t	
Model	Drawing	Α	В	С	D	E	F
MC1.5	Α	1.85	1.62	1.38	0.375	0.24	_
MC2	А	1.85	1.62	1.35	0.375	0.27	-
MC2.5	Α	2.31	2.52	2.23	0.79	0.29	_
MC3	A	2.74	2.22	1.98	0.590	0.24	-
MC4	A	3.23	2.27	2.01	0.98	0.26	-
MC5	А	4.65	3.18	2.64	1.372	0.45	—
MC5.5	Α	5.29	3.21	2.64	1.372	0.57	-
MC6	В	6.05	3.18	2.02	1.372	0.76	0.18
MC6D	В	7.15	5.03	4.06	1.378	0.35	0.21
MC9	В	9.40	4.18	3.49	1.77	0.56	0.13

Bore & Keyseat Sizes

Model	Keyseat	Lockdown Method	G (Bore)	H (Pilot-Both Ends)	l (Both Ends)
MC1.5	None	3/32 Roll Pin	1/4	0.878–0.876 x 0.08 dp	3) 6-32 x 5/16 dp 1.25 B.C.
MC2	None	3/32 Roll Pin	1/4	0.878–0.876 x 0.08 dp	3) 6-32 x 5/16 dp 1.25 B.C.
MC2.5	None 1/8 Key	 2) Set Screws 2) Set Screws 	3/8 1/2	1.655–1.653 x 0.10 dp	3) 10-32 x 7/16 dp 1.875 B.C.
MC3	None None	 2) Set Screws 2) Set Screws 	5/16 3/8	1.383/1.381 x .120 dp	3) 10-32 x 7/16 dp 1.875 B.C.
MC4	None 1/8 Key 3/16 Key	2) Set Screws 2) Set Screws 2) Set Screws	3/8 1/2 5/8	1.854–1.852 x 0.08 dp	3) 10-32 x 7/16 dp 2.375 B.C.
MC5	None 1/8 Key 3/16 Key 3/16 Key 3/16 Key 1/4 Shallow	 2) Set Screws 	3/8 1/2 5/8 3/4 7/8 1	2.441/2.440 x .100 dp	3) 10-32 x 1/2 dp 3.00 B.C.
MC5.5	None 1/8 Key 3/16 Key 3/16 Key 3/16 Key 1/4 Shallow	 2) Set Screws 	3/8 1/2 5/8 3/4 7/8 1	2.441/2.440 x .100 dp	3) 10-32 x 1/2 dp 3.00 B.C. and 3) 5/16–18 x 0.62 dp 3.50 B.C.
MC6	None 1/8 Key 3/16 Key 3/16 Key 3/16 Key 1/4 Shallow	 2) Set Screws 	3/8 1/2 5/8 3/4 7/8 1	2.441/2.440	3) 1/4-20 x 5/16 dp 2.875 B.C.
MC6D	3/16 Key 3/16 Key 3/16 Key 1/4 Shallow	 2) Set Screws 2) Set Screws 2) Set Screws 2) Set Screws 	5/8 3/4 7/8 1	3.250/3.248	3) 5/16-18 x 1/2 dp 4.00 B.C.
MC9	3/16 Key 3/16 Key 3/16 Key 1/4 Key 1/4 Key 1/4 Key	 2) Set Screws 	5/8 3/4 7/8 1 1-1/8 1-1/4	3.250/3.248	3) 5/16–18 x 0.62 dp 3.50 B.C. and 3) 5/16-18 x 1/2 dp 4.25 B.C.

Solid Shaft Configurations





*Thumb screw adjustment

*Spanner wrench adjustment

	manne	, 0010	in aaje	1011101					Spanne	er wrench aujustment	
Model	Drawing	Α	В	С	D (Shaft)	Е	F	G	KEY SEAT	H (Pilot-Both Ends)	l (Both Ends)
MB1	С	0.99	1.37	0.86	3/16	0.51	_	0.170 Flat	_	0.300/0.302 x 0.12 dp	3) 4-40 x 1/4 dp 0.610 B.C.
MB1.5	6 C	1.85	2.36	1.38	1/4	.98	_	0.230 Flat	_	0.876/0.878 x 0.08 dp	3) 6-32 x 5/16 dp 1.250 B.C.
MB2	C C		2.36 2.36	1.35 1.35	1/4 3/8	1.01 1.01	_	0.230 Flat 0.355 Flat	_	0.876/0.878 x 0.08 dp 0.876/0.878 x 0.08 dp	3) 6-32 x 5/16 dp 1.250 B.C. 3) 6-32 x 5/16 dp 1.250 B.C.
MB2.5	•		3.35 3.35	2.23 2.23	3/8 1/2	1.12 1.12	_	0.355 Flat 0.518/0.503	_ 0.125	1.653/1.655 x 0.10 dp 1.653/1.655 x 0.10 dp	3) 10-32 x 7/16 dp 1.875 B.C. 3) 10-32 x 7/16 dp 1.875 B.C.
MB3	С	2.74	3.02	1.98	3/8	1.04	0.04	0.355 Flat	_	1.383/1.381 x 0.12 dp	3) 10-32 x 7/16 dp 1.875 B.C.
MB4	-		2.98 2.98	2.01 2.01	1/2 5/8	0.97 0.97	0.09 0.09	0.518/0.503 0.518/0.503	0.125 0.188	1.852/1.854 x 0.08dp 1.852/1.854 x 0.08dp	3) 10-32 x 7/16 dp 2.375 B.C. 3) 10-32 x 7/16 dp 2.375 B.C.
MB5	С	4.65	4.48	2.64	1	1.75	0.12	0.859/0.844	0.250	2.441/2.440 x 0.100 dp	3) 10-32 x 1/2 dp 3.000 B.C.
MB5.5	6 C	5.29	4.53	2.65	1	1.88	0.25	0.859/0.844	0.250	2.441/2.440 x 0.100 dp	10-32 x 1/2 dp 3.000 B.C. and 5/16-18 x 0.62 dp 3.500 B.C.
MB6	D	6.05	4.48	2.02	1	2.06	0.18	0.859/0.844	0.250	2.441/2.440	3) 1/4-20 x 5/16 dp 2.875 B.C.
MB6D	D	6.95	6.23	4.06	7/8	1.81	0.21	0.771/0.755	0.188	3.250/3,248	5/16-18 x 1/2 dp 4.000 B.C.
MB9	D	9.40	5.39	3.49	1	1.77	0.13	0.859/0.844	0.250	3.250/3.248	5/16-18 x 1/2 dp 5.875 B.C. and 5/16-18 x 1/2 dp 4.250 B.C.

Optional Mounting Bracket

Model	Fits Size	A	В	C	D	E	F	G	H	1
MPB-2B	MB2	0.270	1.750	1.155	0.390	0.280	2.500	0.755	1.500	3.000
	MC2	(6.9)	(44.5)	(29.3)	(9.9)	(7.1)	(63.5)	(19.2)	(38.1)	(76.2)
MPB-15B	MB3/MC3	0.270	2.500	1.155	0.390	0.280	3.500	1.130	2.000	4.000
	MB4/MC4	(6.9)	(63.5)	(29.3)	(9.9)	(7.1)	(88.9)	(28.7)	(50.8)	(101.6
MPB-70B	MB5/	0.270	4.875	1.155	0.390	0.280	6.000	1.630	3.500	6.000
	MC5	(6.9)	(123.8)	(29.3)	(9.9)	(7.1)	(152.4)	(41.4)	(88.9)	(152.4
MPB-120B	MB5.5	0.270	4.875	1.155	0.390	0.280	6.000	1.630	3.500	6.250
	MC5.5	(6.9)	(123.8)	(29.3)	(9.9)	(7.1)	(152.4)	(41.4)	(88.9)	(158.8
MPB-240B	MB6	0.270	4.875	1.155	0.390	0.280	6.500	2.445	4.000	7.500
	MC6	(6.9)	(123.8)	(29.3)	(9.9)	(7.1)	(165.1)	(62.1)	(101.6)	(190.5

All dimensions are nominal unless otherwise noted. () denotes (mm)



Fixed End Cap

≜

Heat Dissipation Charts







MC2.5/MB2.5



MC3/MB3



MC4/MB4



MC5/MB5



MC6D/MB6D



MC5.5/MB5.5



MC6/MB6



MC9/MB9



Torque Setting Charts



1 2 3 4 Unit Torque Settings

5

20 10 0

0

Stub Shaft Adapters

D



- Utilized when "clutch coupling" configuration is desired.
- Comes complete with attachment hardware and drive key.
- Stub shaft adapters should be used in conjunction with a flexible coupling.



Adapter Size	Permanent Magnet Model	А	В	С	D	Е
A1-3/16	MB1	0.9	0.88	3/16	0.18	Flat
A2-14	MB1.5/MC1.5/MB2/MC2	1.60	0.78	1/4	0.15	Flat
A2-58	MB1.5/MC1.5/MB2/MC2	1.60	1.15	5/8	0.15	3/16" Key
A3-38	MB3/MC3	2.36	1.19	3/8	0.19	Flat
A4-38	MB4/MC4	2.86	1.19	3/8	0.19	Flat
A4-58	MB4/MC4	2.86	1.19	5/8	0.19	3/16" Key
A5-1	MB5/MC5/MB5.5/MC5.5	3.45	1.72	1	0.27	1/4" Key
A5-12	MB5/MC5/MB5.5/MC5.5	3.45	1.47	1/2	0.27	1/8" Key
A6-34	MB6/MC6	3.40	1.70	3/4	0.35	3/16" Key
A6D-34	MB6D/MC6D/MB9/MC9	4.65	2.50	3/4	0.50	3/16" Key

*If Solid Shaft Series is used with adapter, thumb screw must be removed and replaced with set screws.

How to Order

1. Torque:

Determine the maximum torque that your application requires. See the application example.

2. Energy Dissipation:

Determine the amount of energy or heat that will be generated during operation. Each clutch or brake is rated for a specific amount of energy, given in units of watts, that it can safely dissipate. Energy calculations for common applications are listed in the applications section.

3. Model Selection:

Select the clutch or brake based on torque and energy requirements. See the specifications under "Heat Dissipation and Torque Setting Charts."

4. Select Bore Size:

Select the proper bore size for the application. Although many standard bores are available, consult the factory if your bore requirement is not listed.

5. Example:

Torque Requirement – 9 lb.in. Energy Requirement – 35 watts Bore Requirement – 5/8 inch Select Model MC5-58

Magnetic Clutches and Brakes



Stainless steel clutches and brakes for harsh environments

Caustic washdown solutions can cause corrosion and eventual failure in food processing applications such as meat and poultry. That's why we have introduced a new line of all stainless steel clutches and brakes. These units, featuring 400 series stainless steel bearings, are robust enough to handle the most hostile washdown environments and tough enough to perform 24/7.



Models In Stock*

Model Size	[Torque	Heat Dissipation (watts)	Inertia (Ibs. sq. in.)	Bending Moment (Ib. in.)	Max. RPM	Weight (Ibs.)	Bore Range/Shaft Dia. (in.)
MC2	0.5–20 oz. in.	10	0.02	5	3600	11 oz.	1/4
MC3	0.3–6.0 lb. in.	18	0.14	10	1800	2	3/8
MC4	0.5–11.0 lb. in	. 22	0.32	10	1800	2.5	3/8, 1/2, 5/8
MB2	1–20 oz. in.	10	0.02	5	3600	11 oz.	1/4
MB3	0.3–6.0 lb. in.	18	0.14	10	1800	2	3/8
MB4	0.5–11.0 lb. in	. 22	0.33	10	1800	2.5	5/8

*Other sizes available upon request.

Magnetic Particle Clutches and Brakes

Accurate torque control with instantaneous engagement!

Warner Electric Precision Tork magnetic particle clutches and brakes are unique because of the wide operating torque range available. Torque to current is almost linear and can be controlled very accurately. The unique features of the magnetic particle clutches and brakes make them ideal for tension control, load simulation, cycling/indexing, and soft starts and stops.

Specials are our business

• Special Shaft Configurations

Customer specified shaft configurations for easy machine mounting and retro-fitting.

• Special Torque

Maximum torque configurations to meet customer specifications.

• *Special Mounting Configurations* Customer specified bolt patterns, special mounting brackets.

• Metric units

Features and Benefits

• Torque independent of slip speed

Torque is transmitted through magnetic particle chains which are formed by an electromagnetic field. The torque is independent of slip speed, depending only on circuit current, and is infinitely variable from 0 (disengaged) to rated torque.

Precise engagement

Precision Tork magnetic particle clutches and brakes engage to transmit torque with speed and precision. Response of the particles to the field is virtually instantaneous, providing perfectly controlled, jerk-free engagement.

Customer specified engagement

Engagement time may be very gradual or extremely fast. The frequency and torque of the engagement/disengagement sequence is limited only by the capabilities of the control circuitry.

• No wearing parts

3

There are no friction surfaces to grab or wear, and the units are not affected by changes in atmospheric or other environmental conditions.

• Efficient/Compact design

High torque to size ratio and low consumption of electric power.

• Versatile mounting

Convenient bolt circle for easy mounting. Mounting brackets available for all sizes. Brakes are available with solid shafts and through bore. Can be mounted horizontally or vertically to solve virtually any motion control requirement.

• Distributor Item

Off the shelf availability. Interchangeable with industry standard sizes.

Design and Operation

The inside story.



Operating Principles

The magnetic particle unit consists of four main components: 1) housing; 2) shaft/disc; 3) coil and 4) magnetic powder. The coil is assembled inside the housing. The shaft/disc fits inside the housing/coil assembly with an air gap between the two; the air gap is filled with fine magnetic powder.



Engagement

When DC current is applied to the magnetic particle unit, a magnetic flux (chain) is formed, linking the shaft/disc to the housing. As the current is increased the magnetic flux becomes stronger, increasing the torque. The magnetic flux creates extremely smooth torque and virtually no "stick-slip".

Disengagement

When DC current is removed the magnetic powder is free to move within the cavity, allowing the input shaft to rotate freely.

Cycling

By turning the current to the coil on and off a cycling effect is achieved.



Selection

Sizing

To properly size magnetic particle clutches or brakes the thermal energy (slip watts) and torque transmitted must be considered. If thermal energy and torque are known for the application select the unit from the charts to the right.

RPM

RPM must be known when calculating thermal energy (slip watts). For load simulation, torque limiting and similar applications, RPM is known. For web handling, the RPM is calculated as follows:

Slip RPM^{*} = $\frac{12 \text{ x Velocity (feet per min.)}}{\pi \text{ x Full Roll Dia.}^{**} (in.)}$

*In rewind applications the motor RPM should be higher (10%) than the fastest spool RPM.

**In applications with the web running over a pulley or in a nip roll application use the pulley diameter as the roll diameter.

Thermal Energy (slip watts)

Tension applications are considered continuous slip applications. When a brake or clutch is slipping, heat is generated. Heat is described in terms of "energy rate" and is a function of speed, inertia, and cycle rate. Heat generated is usually described in terms of thermal energy or slip watts. Starting and stopping applications generate heat when the unit slips during the stopping and starting of the load.

• For continuous slip applications, such as tension control in an unwind or rewind application slip watts are calculated using the following formula:

Slip Watts = .0118 x Torque (lb.in.) x Slip RPM

• For cycling applications heat is generated intermittently, and is calculated using the following formula:

Watts = 2.67 x Inertia (lb.in.²) $x\left(\frac{RPM}{10,000}\right)^2 x F \frac{cycle}{min.}$

Duty Cycle

The average heat input must be below the clutch or brake's heat dissipation rating. If the application generates intermittent heat dissipation, use the average speed for the thermal energy (slip watts) calculations.

Quick Selection Charts







Torque

Tension applications calculate torque as a function of roll radius and tension. Soft/controlled stopping applications calculate torque as a function of inertia, speed and desired time to stop the load. Torque limiting applications calculate torque as the allowable drive through torque. Calculate the torque requirement based on the formulas for the different applications:

• To calculate torque for a web handling application, determine the desired tension in the web then calculate the required torque as follows:

Torque (lb.in.) =

MPB15/MPC15







*Use full roll diameter. In applications with the web running over a pulley or in a nip roll application use the pulley diameter as the roll diameter.

• To calculate torque for soft/controlled stop or cycling applications first determine the inertia (WR²), and apply it to the formula below:

Torque (lb.in.) =	Inertia (Ib.in.2) x RPM
	3,690 x time(s)

Inertia (WR²) =

[(weight of body) x (radius of gyration*)]²

*to calculate for a cylinder about its axis: Solid cylinder = $R^2 = 1/2r^2$ Hollow cylinder = $R^2 = 1/2(r_1^2+r_2^2)$

Selection



Reflected Inertia (rotational)

In mechanical systems it is common for the rotating parts to operate at different speeds. In clutch and brake applications the WR² is calculated for each part operating at different speeds then reduced to and equivalent WR² at the clutch or brake mounting shaft speed. All the rotating parts' WR² are added together and treated as a unit.

The formula for determining the equivalent WR² of a rotating part referred to the clutch or brake shaft is as follows:

$$WR_e^2 = WR^2 x \left(\frac{N}{Ncb}\right)^2$$

Where:

- WR^2 = inertia of the rotating part at N (RPM)
- N = speed (RPM) of the rotating part

N_{cb} = speed (RPM) of the clutch or brake shaft

Reflected Inertia (linear)

In complex systems involving both linear and rotating motion, the linearly moving parts can be reduced to the clutch or brake speed by the following equation:

$$WR^{2}e = W \times \left(\frac{V}{2\pi N}\right)^{2}$$

Where:

W = Weight of body

V = Velocity in feet per minute N = RPM of the clutch or brake shaft

This equation can only be used when the linear speed has a continuous fixed relation to the rotating speed, such as a conveyor driven by a motor.

To determine torque in an overload protection, torque limiting or soft start application use the following equation:

Torque (lb.in.) =
$$\frac{\text{HP x 63,000}}{\text{RPM}}$$

Tension Value Chart

Material	tn (lbs.in. of web width)
Aluminum foils	0.5 to 1.5
	(1.0 aver.)/mil
Cellophanes	0.5 to 1.0/mil
Acetate	0.5/mil
Mylar (Polyester)	0.25 to 0.30/mil
Polyethylene	0.25 to 0.30/mil
Polypropylene	0.25 to 0.30/mil
Polystyrene	1.0/mil
Saran	0.05 to 0.20
	(0.10 aver.)/mil
Vinyl	0.05 to 0.20
	(0.10 aver.)/mil
Paper and Laminations	;
20#/R—32.54 gm/m ²	0.50 to 1.0
40#/R—65.08 gm/m ²	1.0 to 2.0
60#/R—97.62 gm/m ²	1.5 to 3.0
80#/R—130.0 gm/m ²	2.0 to 4.0
Paper	
15 lbs./ream (3,000 sq. ft.)	0.5
20 lbs./ream	0.75
30 lbs./ream	1.0
40 lbs./ream	1.5
80 lbs./ream	2.5
Laminations	
25 lb. paper/.005"	PE 3.0
25 lb. paper/.005" PE/.00032" FOIL/.001" P	
25 lb. paper/.005" PE/.00032" FOIL/.001" P .001" Cello/.0005" PT/.00	21"
25 lb. paper/.005" PE/.00032" FOIL/.001" P .001" Cello/.0005" PT/.00 Cello	01" 1.5
25 lb. paper/.005" PE/.00032" FOIL/.001" P .001" Cello/.0005" PT/.00 Cello When these substrates a	01" 1.5 re coated with
25 lb. paper/.005" PE/.00032" FOIL/.001" P .001" Cello/.0005" PT/.00 Cello When these substrates a polyethylene, nylon polyp	01" 1.5 re coated with ropylene EVA,
25 lb. paper/.005" PE/.00032" FOIL/.001" P .001" Cello/.0005" PT/.00 Cello When these substrates a	01" 1.5 re coated with ropylene EVA, ollowing tension to
25 lb. paper/.005" PE/.00032" FOIL/.001" P .001" Cello/.0005" PT/.00 Cello When these substrates a polyethylene, nylon polyp EAA, and EEA, add the fo	01" 1.5 re coated with ropylene EVA, ollowing tension to
25 lb. paper/.005" PE/.00032" FOIL/.001" P .001" Cello/.0005" PT/.00 Cello When these substrates a polyethylene, nylon polyp EAA, and EEA, add the for the values listed above for only.	01" 1.5 re coated with ropylene EVA, ollowing tension to
25 lb. paper/.005" PE/.00032" FOIL/.001" P .001" Cello/.0005" PT/.00 Cello When these substrates a polyethylene, nylon polyp EAA, and EEA, add the for the values listed above for	01" 1.5 re coated with ropylene EVA, ollowing tension to

Calculating Web Tension

For sizing brakes on applications in which the applied web tension is unknown, use the following information to determine the approximate tension value.

> Applied Web Tension (lbs.) = Approx. Material Tension (lb.in.)

x Roll Width (in.)

Example:

The tension for a twelve inch wide roll of 20# paper stock is unknown. What is the prescribed tension?

Material	tn (lbs.in. of web width)
Cellophane	
.00075"	0.5
.001"	0.75
.002"	1.0
Nylon and Cast Propy (non-Oriented)	lene
.00075"	0.15
.001"	0.25
.002"	0.5
Paperboard	
8 pt.	3.0
12 pt.	4.0
15 pt.	5.0
20 pt.	7.0
25 pt.	9.0
30 pt.	11.0
Mylar and Oriented Pr	opylene
0.0005"	0.25
0.001"	0.5
0.002"	1.0
Material	tn (lbs./strand)
Aluminum Wire	
#20 AWG	4.00
#18 AWG	5.50
#16 AWG	9.00
#14 AWG	10.00
#12 AWG	12.00
#10 AWG	15.00
#8 AWG	25.00
Copper Wire	
#20 AWG	8.00
#18 AWG	10.00
#16 AWG	12.00
#14 AWG	15.00
#12 AWG	18.00
#10 AWG	20.00
#8 AWG	25.00

Solution:

The approximate tension value as noted in the chart above for 20#paper stock is 0.75 lb.in.; thus the tension for this application is (0.75 lb.in. x 12) = 9 lbs.

Applications

Warner Electric Precision Tork magnetic particle clutches and brakes are the ideal solution for controlling and maintaining torque. If the application is tensioning, load simulation, torque limiting, or soft starts and stops the magnetic particle unit is the preferred torque controlling device.

Typical Applications

- · Wire Processing (winding, hooking, cutting)
- Paper/Foil/Film Processing
- Labeling Applications
- Textile Processing
- Material Processing
- · Load profile simulation on:
- Exercise Equipment
- Flight Simulators
- Healthcare Equipment
- Life testing on:
- Motors
- Gears
- Pulleys
- Belts
- Chains
- Many other Rotating Devices
- Conveyors
- Bottle Capping

Controlled Acceleration/Deceleration



Controlled soft stop

Particle brakes and the MCS-153 control provide soft stopping of large rotating loads. By controlling the input current, the load is decelerated in a controlled manner without torque spikes, shock, or vibration.

Application Example:

Information Required:						
RPM: 1,000						
Time to Stop:	3 seconds					
Inertia*:	400 lb.in. ²					

*If inertia is not known see page 3 to calculate.

How to Size:

Maximum Torque (lb.in.) =

$$= \frac{\text{Inertia (lb.in.2) x RPM}}{3,690 \text{ x time(s)}}$$

$$= \frac{400 \times 1,000}{3,690 \times 3}$$

36 lb-in =

Select a brake that exceeds the maximum torque requirements from the Specification Chart - MPB70.

Controlled soft start

Particle clutches and the MCS-153 control provide soft controlled acceleration to prevent tipping or shock during start up.

Application Example:

Information Required: RPM: 500 Time to Start: 4 sec. 50 lb.in.² Inertia*:

*If inertia is not known see page 3 to calculate

How to Size:

Maximum Torque (lb.in.) =

$$= \frac{\text{Inertia (lb.in.2) x RPM}}{3,690 \text{ x time(s)}}$$

50 x 500

- 3,690 x 4
- 1.7 lb.in. =

Select a clutch that exceeds the maximum torque requirements from the Specification Chart - MPC2.



Applications

Tensioning

Magnetic Particle clutches and brakes offer smooth controlled torque for tensioning in both the unwind zone and rewind zone. Torque produced from the magnetic particle clutches and brakes is independent of slip speed, offering a distinct advantage over competing technologies. Since torque can be varied infinitely by varying the input current, the magnetic particle clutches and brakes are ideal in an open loop system. To close the loop in the tensioning system,

combine the magnetic particle clutch or brake with a Warner[®] sensor and control, resulting in more precise control of tension.



Unwind stand under load cell control

Particle brakes and the TCS-240 load cell control with precision load cell sensors provide closed loop tension control.

Application Example:

Information Required:							
Full Roll Diameter: 20 inches							
Tension:	5 lbs.						
Velocity:	400 fpm						

How to Size:

Maximum Torque (lb.in.) = <u>Full roll diameter (in.) x tension (lbs.)</u> 2 20 x 5

 $=\frac{20 \times 5}{2}$

2 50 lb in

= 50 lb.in.

Slip RPM = $\frac{\text{Velocity (fpm) x 12}}{\text{Full roll diameter x }\pi}$
Full roll diameter x π
$=\frac{400 \times 12}{20 \times \pi}$
= 76 RPM

Thermal Energy (Slip Watts) = .0118 x Torque (lb.in.) x RPM = .0118 x 50 x 76 = 45 Watts

Select a brake that exceeds the maximum torque and thermal energy requirements from Quick Selection Chart – MPB70.

Rewind stand under dancer control

Particle clutches and the MCS-203 control provide accurate closed loop tension control for rewind applications.

Application Example:

Information Required: Core Diameter: 3 inches Full Roll Diameter: 9 inches Tension: 5 lbs. Velocity: 300 fpm Input RPM: 500 RPM* Maximum Torque (lb.in.) = tension (lbs.) x full roll diameter (in.) 2 = <u>5 x 9</u> 2 = 23 lb-in Core RPM = $\frac{12 \times \text{Velocity}}{12 \times \text{Velocity}}$ (fpm) π x (core diameter) = <u>12 x 300</u> πхЗ = 382 RPM Full Roll RPM = $\frac{12 \times \text{Velocity (fpm)}}{12 \times \text{Velocity (fpm)}}$ π x Full Roll Dia. = <u>12 x 300</u> **π x 9** = 127 RPM Slip RPM = Input RPM - Full Roll RPM = 500 - 127= 372.68Thermal Energy (slip watts) = = .0118 x Torque x Slip RPM = .0118 x 22 x 373 = 99 watts

Select a clutch that exceeds the maximum torque and thermal energy requirements from the Quick Selection Chart – MPC120.

*To maximize tension control and minimize heat generated, select a drive system that will result in an actual input speed as close to, but not less than, 30 RPM greater than the core RPM. In this example, 382 + 30 = 412, would be ideal but 500 RPM was more readily available.

Torque Limiting/ Overload Protection

The magnetic particle clutches and brakes combined with a Warner[®] CBC control are effective means to providing protection in the case of jam ups. The magnetic particle clutch and the CBC control can provide precise adjustable torque in torque limiting applications.

Application Example

Information Required: Motor HP: 1 HP Motor RPM : 700 RPM

How to Size:

Maximum Torque (lb.in.) =

- $= \frac{HP \times 63,000}{RPM} \\ = \frac{1 \times 63,000}{1 \times 63,000}$
- 700
- = 90 lb.in.

Select a clutch that exceeds the maximum torque requirements from the Selection Chart – MPC120.

Load Simulation

By combining the magnetic particle brake with a microprocessor control, virtually any load simulation can be obtained. The control is programmed with the profile or condition that is to be simulated. The control then feeds the profile to the magnetic particle brake in terms of input current. The brake reads the input current and provides load torque to simulate the condition.

If the application requires programming load profiles, adjusting load torque, or simulating friction or drag loads, the magnetic particle clutches and brakes are the ideal solution.



Exercise Equipment

Brake models provide a smooth controllable resistance for exercise machines. When integrated with a microprocessor control, programming load profiles is possible.



Dimensions and Specifications

Clutches



Dimensions

Model	A	В	C	D	E	F	G (Output)	H (Input)	I	J	K5
MPC2-1	2.11	0.750/0.749	3.73	1.85	0.06	1.16	0.88	0.88	0.2498/0.2492	(3) #6-32 x 0.50 on 1.350 BC	Flat
MPC15-1	2.96	1.125/1.124	4.93	2.80	0.07	1.69	1.00	1.00	0.4998/0.4992	(3) #8-32 x 0.50 on 2.000 BC	Flat
MPC15-2	2.96	1.125/1.124	5.08	2.80	0.07	1.69	1.22	0.92	0.3748/0.3742	(3) #8-32 x 0.50 on 2.000 BC	Flat
MPC25-1	2.96	1.125/1.124	4.93	2.80	0.07	1.69	0.995	1.00	0.4998/0.4992	(3) #8-32 x 0.50 on 2.000 BC	2 Flats at 90°
MPC25-2	2.96	1.125/1.124	5.08	2.80	0.07	1.69	1.22	0.92	0.3748/0.3742	(3) #8-32 x 0.50 on 2.000 BC	2 Flats at 90°
MPC70	4.58	1.625/1.624	6.55	3.67	0.10	2.08	1.35	1.35	0.7497/0.7492	(3) #10-32 x 0.63 on 4.228 BC	0.188 Keyway
MPC120	5.25	1.625/1.624	7.02	4.00	0.10	2.40	1.50	1.35	0.7497/0.7492	(3) #1/4-20 x 0.75 on 4.812 BC	0.188 Keyway

Specifications

Model Number	Max. Drag Torque O Excit. (Ib.in.)	Rated Torque (Ib.in.)	Rated Voltage	Resistance (Ohms)	Rated Current (Amps)	Response Zero Force (Millisec)	Response With Force (Millisecs)	Inertia of Output Shaft (Ib.in.²)	Max. Heat Dissipation (watts)	Max. Speed Recom. (RPM)	Weight
MPC2	0.40	2	24	92	0.261	8	4	0.001	10	1,800	2
	0.40	2	90	1552	0.058	8	4	0.001	10	1,800	2
MPC15	0.40	15	24	80	0.302	25	9	0.013	20	1,000	5.5
	0.40	15	90	1501	0.060	25	9	0.013	20	1,000	5.5
MPC25	0.40	25	24	45	0.533	25	9	0.013	20	1,000	5.5
MPC70	1.00	70	24	35	0.677	70	17	0.073	100	1,000	16
	1.00	70	90	613	0.147	70	17	0.073	100	1,000	16
MPC120	2.00	120	24	33	0.742	90	25	0.370	140	1,000	22
	2.00	120	90	475	0.190	90	25	0.370	140	1,000	22

Optional Mounting Bracket (for mounting MPB Brakes and MPC Clutches)



Model	Fits Size	A	В	C	D	E	F	G	Н	I
MPB-2B	2	0.270 (6.9)	1.750 (44.5)	1.155 (29.3)	0.390 (9.9)	0.280 (7.1)	2.500 (63.5)	0.755 (19.2)	1.500 (38.1)	3.000 (76.2)
MPB-15B	15, 25	0.270 (6.9)	2.500 (63.5)	1.155 (29.3)	0.390 (9.9)	0.280 (7.1)	3.500 (88.9)	1.13 (28.7)	2.000 (50.8)	4.000 (101.6)
MPB-70B	70	0.270 (6.9)	4.875 (123.8)	1.155 (29.3)	0.390 (9.9)	0.280 (7.1)	6.000 (152.4)	1.63 (41.4)	3.500 (88.9)	6.000 (152.4)
MPB-120B	120	0.270 (6.9)	4.875 (123.8)	1.155 (29.3)	0.390 (9.9)	0.280 (7.1)	6.000 (152.4)	1.63 (41.4)	3.500 (88.9)	6.250 (158.8)
MPB-240B	240	0.270 (6.9)	4.875 (123.8)	1.155 (29.3)	0.390 (9.9)	0.280 (7.1)	6.500 (165.1)	2.245 (62.1)	4.000 (101.6)	7.500 (190.5)

All dimensions are nominal unless otherwise noted. () denotes (mm)

Dimensions and Specifications

Brakes





Dimensions

Model	A	В	C	D	E	F	G	H	l (Shaft)	J (Bore)	K	L
MPB2-1	2.11	0.750/0.749	2.23	1.15	0.06	0.70	0.87	_	0.2498/0.2492	_	#6-32 x 0.27 on 1.350 BC	1 Flat
MPB15-1	2.96	1.125/1.124	3.05	1.46	0.07	0.85	1.35	_	0.3748/0.3742	-	#8-32 x 0.30 on 2.000 BC	2 Flats at 90°
MPB15-2	2.96	1.125/1.124	2.05	1.46	0.07	0.85	0.34	0.18	-	0.375/0.376	#8-32 x 0.30 on 2.000 BC	0.125 Thru Hole
MPB15-3	2.96	1.125/1.124	2.70	1.46	0.07	0.85	0.99	_	0.4998/0.4992	-	#8-32 x 0.30 on 2.000 BC	2 Flats at 90°
MPB25-1	2.96	1.125/1.124	2.05	1.46	0.07	0.85	1.35	_	0.3748/0.3742	-	#8-32 x 0.30 on 2.000 BC	2 Flats at 90°
MPB25-2	2.96	1.125/1.124	2.05	1.46	0.07	0.85	0.34	0.18	-	0.375/0.376	#8-32 x 0.30 on 2.000 BC	0.125 Thru Hole
MPB25-3	2.96	1.125/1.124	2.7	1.46	0.07	0.85	0.99	_	0.4998/0.4992	-	#8-32 x 0.30 on 2.000 BC	2 Flats at 90°
MPB70-1	4.57	1.625/1.624	2.62	1.76	0.10	0.98	0.50	0.18	-	0.500/0.501	#10-32 x 0.50 on 4.228 BC	0.125 Thru Hole
MPB70-2	4.57	1.625/1.624	3.37	1.76	0.10	0.98	1.25	-	0.7497/0.7492	_	#10-32 x 0.50 on 4.228 BC	0.188 Keyway
MPB120-1	5.25	1.625/1.624	4.02	2.17	0.10	1.18	1.50	0.50	-	0.500/0.501	#1/4-20 x 0.75 on 4.812 BC	0.156 Thru Hole
MPB120-2	5.25	1.625/1.624	4.02	2.17	0.10	1.18	1.50	-	0.7497/0.7492	_	#1/4-20 x 0.75 on 4.812 BC	0.188 Keyway
MPB240-1	6.23	2.441/2.440	4.66	2.65	0.10	1.46	1.65	_	0.7497/0.7492	_	#1/4-20 x 0.65 on 5.875 BC	0.188 Keyway
MPB240-2	6.23	2.441/2.440	3.51	2.65	0.10	1.46	0.50	_	-	0.875/0.876	#1/4-20 x 0.65 on 5.875 BC	0.188 Keyway
MPB240-3	6.23	2.441/2.440	3.51	2.65	0.10	1.46	0.50	-	_	1.000/1.001	#1/4-20 x 0.65 on 5.875 BC	0.250 Shallow Keyway

Specifications

Model Number	Max. Drag Torque O Excit. (Ib.in.)	Rated Torque (Ib.in.)	Rated Voltage	Resistance (Ohms)	Rated Current (Amps)	Response Zero Force (Millisec)	Response With Force (Millisecs)	Inertia of Output Shaft (Ib.in.²)	Max. Heat Dissipation (watts)	Max. Speed Recom. (RPM)	Weight
MPB2	0.40	2	24	92	0.261	8	4	0.001	10	1,800	1
	0.40	2	90	1552	0.058	8	4	0.001	10	1,800	1
MPB15	0.40	15	24	80	0.302	25	9	0.013	20	1,000	2.5
	0.40	15	90	1501	0.060	25	9	0.013	20	1,000	2.5
MPB25	0.40	25	24	45	0.533	25	9	0.013	20	1,000	2.5
MPB70	1.00	70	24	35	0.677	70	17	0.073	100	1,000	8
	1.00	70	90	613	0.147	70	17	0.073	100	1,000	8
MPB120	2.00	120	24	33	0.742	90	25	0.370	140	1,000	12.5
	2.00	120	90	475	0.190	90	25	0.370	140	1,000	12.5
MPB240	4.00	240	24	19	1.286	150	45	1.311	200	1,000	20.5
	4.00	240	90	246	0.366	150	45	1.311	200	1,000	20.5

Controls

Adjustable Torque



TCS-200-1 Manual/Analog

The TCS-200-1/-1H single channel controls are selectable voltage or current controlled power supplies designed to power up to a 16-magnet Electro Disc tension brake system, Electromagnetic Particle Brakes, TB Series brakes, or Advanced Technology tension brakes. These controls operate from a switchselectable power source of 115 or 230 VAC. They can be operated manually from the front panel or remotely via an analog voltage input, a current input, a remote pot, or a roll follower. External inputs are also provided for remote brake Off, Run, and Stop functions, as well as front panel control of these functions.

System Control





CBC200/CBC300

The CBC 200 and CBC 300 are Constant Current controls for 90 volt coil clutches and brakes. Both can control a single clutch or brake, or a clutch and brake or two clutches or two brakes.

Both operate based on 120 volt AC input. The CBC 200s have one output channel adjustable and one fixed. The CBC 300s have both channels adjustable.

The CBC 200 and CBC 300 provide for potentiometer adjustment on the front of the unit as shown.

The CBC 200-1 and CBC 300-1 provides for input from an external 10K ohm, 2 watt potentiometer.

The CBC 200 C1 and CBC 300 C1 are chassis mount versions of the CBC 200-1 and CBC 300-1.

Features

- Input: 115/230 VAC, 50/60 Hz
- Output: -1, 0–24 VDC adjustable, 4.25 Amps continuous
 -1H, 0–24 VDC adjustable, 5.8 Amps continuous
- · Front panel torque adjust
- Front panel brake mode stop switch Modes: Stop – Brake Full On Run – Normal Operation Off – Brake Off
- Remote brake mode switch (same functions as mentioned above)
- Remote torque adjust
- Roll follower input
- 0–10 VDC analog voltage input
- 4–20mA analog current input

Features

- Input: 115 VAC 50/60 hz
- Output: Pulse width modulated full wave rectified DC. Constant current, switch selectable ranges designed for 90 volt DC clutches and brakes.
- Circuit Protection: Internal short circuit protection on outputs, but no circuit protection for AC ground faults. Customer supplied 1.5 amps 250 VAC Fast Acting type fuse recommended.
- Status Indicators: "POWER" green LED indicating AC power is applied to the control. "SHORT" red LED indicating that a short circuit condition exists on one or both of the outputs.
- Enclosure: NEMA 1 rated.
- External switching: Mechanical or Electromechanical switching. Customer supplied 1 amp, 125 v minimum rating

Dancer/Remote Analog Control



MCS-203/MCS-204/ MCS-166

The MCS-203 is a basic dancer control that automatically controls web tension through the use of a dancer roll and sensor. It is single channel, but can operate two 24 VDC tension brakes in parallel when using two MCS-166 power supplies.

The MCS-204 is a basic remote analog control that can also be operated manually via a front panel tension adjustment potentiometer. It is also single channel with the possibility of operating two 24 VDC tension brakes in parallel when using two MCS-166 power supplies.

Features

- Input: 115/230 VAC, 50/60 Hz
- Output: 0–24 VDC at 3 Amps max. MCS-203 (only)

- Full P-I-D adjustment
- System gain display

MCS-204 (only)

- Front panel torque adjustment
- Remote potentionmeter adjustment
- Roll follower input
- Remote voltage or current analog signal following

Magnetic Capping Headset Replacements

Offering 100% Interchangeable Capping Heads on Major OEM Machines to Capping Users

Featuring Hysteresis Magnet Technology

The new Warner Electric ABC2000™ screw capping headset is a drop-in replacement for less reliable capping headsets purchased from the OEM. The ARC2000[™] headsets hysteresis magnet technology, the most efficient torque control technology on market.



ZRC2000 (Replaces Zalkin)

Smooth Torque

- Reduces wear on the headset and machine components.
- · Eliminates over tightening.
- · Consistent removal torque.





50

ARC2000 Capping Headset Advantages

Features and Benefits

• Top Load Spring Setting Scale

Easily and quickly adjust top load force to the same level on a group of headsets.

• Smooth Magnetic Torque

Smooth application torque eliminates cap over tightening caused by pulsating torque designs.

Oversized Thrust Bearing

Significant increase in bearing life leads to a significant reduction in maintenance cost.

Stainless Steel Construction

Units will withstand harsh environments, including caustic washdown.

• Models available for direct replacement of OEM headsets

No machine modification required. Replacement headsets bolt-up directly where the old one came off.

• *Smooth Magnetic Torque* Reduces wear on other machine components caused by pulsating torque.

• *Application Torque Setting Scale* Easier to set and maintain headsets.



Takes the guesswork out of setting top load force

Easy Rebuilds!

- Full rebuild kits available
- No expensive maintenance contracts
- Save time and money by repairing the headsets yourself

Repair Kits	Model
Bearing Repair Kit	M4.5-RK1
Magnet Repair Kit	M4.5-RK2

Many Warner headsets available off the shelf!

Replacement Headsets for Alcoa OEM Machines

Alcoa Model	Warner Model
Magna Torq	M4.5-001
Magna Torq2000	M4.5-002
VK560	M4.5-007

Replacement Headsets for Other Major OEM Machines

	Warner Models
Zalkin	M4.5-025 M4.5-035
Fogg	M4.5-004 M4.5-034
AROL	M4.5-010 M4.5-027 M4.5-032

ALTRA INDUSTRIAL MOTION

Warner Electric

Electromagnetic Clutches and Brakes and Linear Actuators - USA

South Beloit, IL 61080 815-389-3771

For application assistance: 1-800-825-9050

Electromagnetic Clutches and Brakes - Europe Allonnes, France +33 (0)2 43 43 63 63

Precision Electric Coils and Electromagnetic Clutches and Brakes - USA Columbia City, IN 46725 260-244-6183

Inertia Dynamics

Spring Set Brakes; Power On and Wrap Spring Clutch/Brakes Torrington, CT 06790 860-482-4444

Matrix International

Electromagnetic Clutches and Brakes, Pressure Operated Clutches and Brakes Brechin, Scotland +44 (0) 1356 602000

Huco Dynatork

Precision Couplings and Air Motors Hertford, UK +44 (0) 1992 501900

Boston Gear

Enclosed and Open Gearing, Electrical and Mechanical P.T. Components Quincy, MA 02171 617-328-3300

For Customer Service: 1-888-999-9860

For Application Assistance: 1-800-816-5608

Formsprag Clutch

Overrunning Clutches and Holdbacks Warren, MI 48089 586-758-5000

For application assistance: 1-800-927-3262

Marland Clutch

Roller Ramp and Sprag Type Overrunning Clutches and Backstops Burr Ridge, IL 60527 630-455-1752

Stieber Clutch

Overrunning Clutches and Holdbacks Heidelberg, Germany

+49 (0)6221 30 47 0 Saftek Friction

Non-asbestos Brake and Clutch Materials Telford, Shropshire UK 01952 581122

Wichita Clutch and Industrial Clutch

Pneumatic and Oil Immersed Clutches and Brakes - USA Wichita Falls, TX 76302 940-723-3400

Pneumatic Clutches and Brakes - Europe Bedford, UK +44 (0)1234 350311

Twiflex I imited

Caliper Brakes and Thrusters Twickenham, Middlesex UK +44 (0) 20 8894 1161

Ameridrives Couplings

Gear Couplings, Mill Spindles, Universal Joints Erie, PA 16512 814-480-5000

Bibby Transmissions

Disc, Gear, Grid Couplings, Overload Clutches West Yorkshire, UK +44 (0) 1924 460801

Nuttall Gear and **Delroyd Worm Gear**

Worm Gear and Helical Speed Reducers Niagara Falls, NY 14302 716-298-4100

Altra Industrial Motion -Asia Pacific and Africa

China	852 2615 9313
Taiwan	886 2 2577 8156
Singapore	65 487 4464
Thailand	66 2 322 0481
Australia	612 9894 0133
S. Africa	27 11 918 4270

www.warnerelectric.com



Warner Electric LLC

449 Gardner Street • South Beloit, IL 61080 815-389-3771 • Fax: 815-389-2582 www.warnerelectric.com